AWARNING

SuperLift Swivel Alloy Hooks



TO AVOID SEVERE PERSONAL INJURY OR DEATH:

NEVER HOIST LOADS OVER OR NEAR PEOPLE.

NEVER WORK UNDER OR NEAR HOISTED LOADS.

NEVER EXCEED WORKING LOAD LIMIT.

NEVER REPAIR, ALTER, REWORK OR RESHAPE A HOOK/BOW BY WELDING,

HEATING, BURNING OR BENDING.

NEVER HAVE THE LOAD BE LIFTED SUPPORTED BY THE LATCH

NEVER SUBJECT HOOK TO SIDE LOADS, BACK LOADS OR TIP LOADS.

ALWAYS PUT SAFETY FIRST READ SAFETY PRECAUTIONS. **ALWAYS** DETERMINE LOAD (TONNES) PRIOR TO LIFTING.

ALWAYS USE THE RIGHT CAPACITY SWIVEL HOOK FOR THE LOAD.

ALWAYS SUPPORT THE LOAD WITH THE HOOK.

ALWAYS OPERATE, INSPECT AND MAINTAIN THIS EQUIPMENT IN

ACCORDANCE WITH ALL RELEVANT SAFETY STANDARDS.

MAKE THE FOLLOWING CHECKS PERIODICALLY TO ENSURE SAFE USE (IDEALLY PER WEEK)

CHECK MAIN ASSEMBLY AND PARTS FOR DEFORMATION.

DISCARD IF THERE IS ANY DISTINCT DEFORMITIES EG. NICKS, CRACKS, WEAR, GOUGES AND DEFORMATION.THIS WILL OCCUR IF THE PRODUCT IS

OVERLOADED OR USED INCORRECTLY.

